

# Oil Field Environmental Incident Summary

**Incident:** 20151208140601      **Date/Time of Notice:** 12/08/2015 14:06

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** BB-SIVERTSON- 151-95-2019H-5

**Field Name:** BLUE BUTTES

**Well File #:** 30083

**Date Incident:** 12/8/2015

**Time Incident:** 03:45

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 95

**Sec:** 17

**Qtr:**

**Location Description:**

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Troy Brunsell  
3015 16TH ST SW STE 20  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:** 0.3 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

**Spilled Units**

**Recovered Units**

**Followup Units**

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

Fire

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There is no immediate risk to report at this time. The fire has been extinguished.

**Areal Extent:**



**Potential Environmental Impacts:**

There are no potential environmental impacts to report at this time. The fire has been extinguished.

**Action Taken or Planned:**

The operator used a fire extinguisher to extinguish the fire. Aggreko has been dispatched to remove and replace the generator on location.

**Wastes Disposal Location:** If any of the generator components need to be disposed of, they will be disposed of at an approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 12/9/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, a fire began on the constructed well site and was contained to the well site. NDIC retains oversight.